

NOTE:

- > In Fire Zone 4 (Very High Fire Hazard Severity Zone), exterior glazing shall be MULTI-PANE units with a minimum of ONE TEMPERED PANE, or glass block units, or minimum 20-min. rated or complies with SFM12-7A2.
- > Replacement windows with exact same size and location with SHGC factor of 0.23 or better & U-factor of 0.30 or better.
- > The proposed windows do not include alteration of existing header(s) and wall framing immediately below the opening.
- > Every sleeping room shall have at least one operable emergency escape and rescue door or window opening. Replacement windows shall be exempt from the requirements of Section 1030.2, 1030.3 and 1030.5 provided the replacement window meets the following conditions: 1. The replacement window is the manufacturer's largest standard size window that will fit within the existing frame or existing rough opening. The replacement window shall be permitted to be of the same operating style as the existing window or a style that provides for an equal or greater window opening area than the existing window. 2. The replacement of the window is not part of a change of occupancy.